

Care & Cleaning Kool Deck[®], Kool Deck[®] Elite[™], Designer Color[™] surfaces.



AFTER INSTALLATION

Kool Deck[®] surfaces need sufficient time to cure. The owner should avoid contact with the deck for 48 hours, light walking traffic after 3 days; normal walking traffic after 14 days; heavy patio furniture after 28 days.

MAINTENANCE

Kool Deck surfaces can provide years of beauty and durability, but does require cleaning on a regular basis. Kool Deck surfaces should be cleaned by using strong soap and water and a nylon bristle broom to scrub the surface and then rinsed clean with a garden hose. Do not allow dirt, leaves, etc. to remain on the surface for long periods of time. If you have a salt water chlorinator, it is essential that you rinse and clean your deck frequently. Regular cleaning of your Kool Deck surface is an important part of the success of your deck.

SPILLS

Any spills should be rinsed off and washed immediately. Spills that could result in a stain should be scrubbed immediately using strong soap and water and a nylon scrub brush and then rinsed with water. Build-ups of oil type stains such as suntan lotion, body oils, etc. can be easily cleaned with this procedure. Note: Use care when handling any concentrated pool chemical such as muriatic acid, chlorine, etc. If you should accidentally spill any such chemical on your deck, rinse the area thoroughly and immediately. Chemical fertilizers used on lawns and gardens can leave stains when such fertilizers are water activated. After fertilizing, wash your deck to remove any chemical that may have been scattered on the deck.

MINERAL DEPOSITS

Experienced Contractors Only: Gray mineral deposits can collect on the deck over a period of time in heavily used areas such as at steps, diving board areas, etc. These deposits are caused by water evaporating from the deck, leaving behind minerals. Annual buffing of the deck can remove mineral build up. Buffing can be done with a rented commercial floor-buffing machine (the kind with the single rotary wheel). Place a 3M 19" Scotch Brite brown stripper floor pad (or equivalent) under the wheel. Wet the deck and buff. Be sure to keep the deck wet while buffing. Note: Buffing should not be attempted by anyone who is not handy with machinery or is not physically strong. Contact a contractor if you feel you need assistance. Attention: The deck owner should not attempt Muriatic acid washes. Contact a service professional for such cleaning jobs. Acid baths are not necessary or recommended as part of a general maintenance cleaning procedure for Kool Deck surfaces. General cleaning and maintenance is best accomplished by using the methods suggested in the above paragraphs.

The manufacturer offers this product and Information in good faith, but without guarantee either expressed or implied, as conditions and methods of use of our product are beyond our control.